


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 17, Township 9 North, Range 1 West,

Monument Description & Remarks: 5/8" Rebar W/ BTR Cap Set On W. Edge of 0.3' x 0.6' Sandstone Badly Deteriorated.




COMPLETED BY Stu V. Fankler

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E. Bledsoe

Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD



STATE OF INDIANA - COUNTY OF MONROE

SECTION 17, TOWNSHIP 9 NORTH, RANGE 1 WEST

MONUMENT DESCRIPTION & REMARKS

FOUND POINTED SET ROCK IN EXISTING FENCE LINE
(MEASUREMENTS ARE TO ROOFING NAILS SET IN TREES)

RECOVERY TIE DRAWING



STATE OF INDIANA
COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 20 TH DAY OF JANUARY, 1983 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____
OR _____

TOWNSHIP:
BLOOMINGTON

UNITED STATES GOVERNMENT AGENCY

CORNER I.D.

TITLE



Blm G-09